

# Daily Quality Control Report



## PROJECT: Rio Puerto Nuevo 103 | PAN AM

This report will contain a description of the work performed, samples collected, general conditions, corrective action taken, departures from the sampling plans and any other notes or comments needed that will document the day's activities.

ANAMAR Environmental Consulting, Inc.  
2106 NW 67th Place Suite 5  
Gainesville, FL 32653  
(352) 377-5770

Name: ME  
Date: 12/4/18 - 12/5/18

Samples Collected: PN18-5W, PA18-2A, PA18-2B, PA18-3 A or B  
PA18-4 A or B  
PA18-1 A or B

### Notes, Comments:

0630-0830 - Collected PN18-5W

0830-1130 - Meet w/ PAN AM client to go over 50-w and project depth

1130-1730 Collected samples at PAN AM Grain Facility. The goal was to collect samples from -34 feet and -38 feet. However, at every station but 2, we had refusal well above the -34 project depth.

PA18-4 - had clay layer at -28 feet, consulted w/ EPA about inability to collect a core at this station. EPA agreed to let us collect a sample at surface w/ grab sampler. (A or B)

PA18-3 Had hard refusal/rock at 2 feet of penetration (-33.7 feet). Consulted w/ EPA about inability to collect core. EPA agreed to let us collect a sample at surface w/ grab sampler. (A or B)

PA18-2 Able to collect a <sup>core</sup> sample for both A (-34) and B (-38) Able to reach -38 feet project depth

12/5/18 0700 to 0830 PA18-1 Had to move station from original location to find a small shoal above -34 feet project depth. We drove around the area to find a shoal near the very first mooring dolphin near last line of bathymetric soundings provided by client. Had hard refusal/rock before reaching -34 feet project depth. Collected one set of core samples at this location (A or B)

# Daily Quality Control Report



**PROJECT:** ~~Rio Puerto Nuevo 103~~ PAN AM

This report will contain a description of the work performed, samples collected, general conditions, corrective action taken, departures from the sampling plans and any other notes or comments needed that will document the day's activities.

ANAMAR Environmental Consulting, Inc.  
2106 NW 67th Place Suite 5  
Gainesville, FL 32653  
(352) 377-5770

Name: JK  
Date: 12/5/18

Samples Collected: PA18-1 A or B

Notes, Comments:

0700-0900 Collected last sample at PAN AM dock (see 12/4/18)  
DQCR for notes on sample collection

0900-1730 Composited samples, organizing samples into  
coolers for shipment, cleaning up and  
packing up equipment, filling out chain  
of custody